



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 08/26/2014

Reviewed

[Signature]

Mine Name: South Farm	Permit Number: S/035/0030	Mine Status: Approved
Operator Name: R.A. Johnson	Inspection Date: 08/18/2014	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 2:30 PM	Bond Amount: \$5,000
Attendee(s): Blake Thomas-Herriman, Robert Johnson-Opt	Weather: Sunny, Dry	Bond Escalation: 10/15/2010
Inspection Purpose: Operator requested bond release		Prior Inspection: none

Conclusions and Recommendations

This site has NOT been reclaimed and the bond would not normally be returned to the operator by OGM, but the site is under a future Herriman City roadway which has a developers construction bond held by Herriman City. A roadway bonded by the city is a post mining land use. Documentation from Herriman City is attached regarding bond release. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit fee is up to date, no transfers were requested, bond escalation is past due as shown above.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Small pit was on site with oversteepended walls.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No external drainage problems were noted, but weather was dry.		
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Cast concrete pipe was on site - no rebar reinforcement in noted in pipe, no deleterious materail was noted		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roads were in fair condition, no dust suppression at the time of construction		
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No concurrent reclamation was noted at the time of inspection. Mine site is the future site of a Herriman City roadway		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No regrading at the site at the time of inspection		
8. <i>Soils</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No soil stockpiles are noted at the time of inspection		
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No new revegetation was noted		
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
This line is intentionally left blank		

Inspector's Signature:

[Signature]

CC: Herriman City - BThomas@Herriman.org, Operator - Robert Johnson

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M035-SaltLake/S0350030-SouthFarms/inspections/INSP-08182014a.pdf





Access road from above



Mine site - photo taken from Mountain view corridor



Mine site - photo taken from Mountain view corridor



Mine site - photo taken from Mountain view corridor